

SERVICE BULLETIN 01/2014

Bulletin Number: 01/2014

Issue Date: 11th August 2014

Subject: GP One – never exceed speed limitation

Classification: Informative

Airplanes Affected (s.n.): GP One, all flying aircrafts

Page: 1 of 1

Compliance: After receive of this Service Bulletin

Reason: Flying at high airspeed can cause aircraft buffering and dangerous symptoms of flutter


Description: During flight test program it was established, that flying on top airspeed (approaching never exceed speed) can cause dangerous symptoms of flutter.

Action: Immediately perform an Airspeed indicator (ASI) re-marking to never exceed speed decrease to 80kt - via attached picture (in the bottom of letter).

Availability: -

Annexe:

- Photo of the Airspeed indicator (ASI)



Manufacturer: JIHLAVAN airplanes, s. r. o., Znojemská 64, 58601 Jihlava, Czech Republic
Web: www.skyleader.aero; E-mail: support@skyleader.aero