



## INFORMATION BULLETIN 01/2021

**Information Bulletin Number:** 01/2021

**Issue Date:** 6th September 2021

**Subject:** Increasing the range of permitted in flight CG positions.

**Classification:** Informative, voluntary

**Airplanes Affected (s/n):** All JA-600 (Skyleader 600)

**Compliance:** After approval by the manufacturer

**Reason:** To increase the utility value of the aircraft while maintaining operational safety, calculations and tests were performed to extend the permitted position of the aircraft's center of gravity from the original value of 20-30% MAC to the new range of 20-35% MAC.

**Description:** Modification of the airplane Flight Manual (Pilot Operating Handbook) and labels (if prescribed).

**Action:**

- Contact the aircraft manufacturer (he will assess the possibility of change with regard to local regulations)
- After approval by the manufacturer, rewrite/replace the affected pages in the Flight Manual (Pilot Operating Handbook) and any labels on the airplane (if prescribed)
- Enter the change in the change page of the Flight Manual (Pilot Operating Handbook)

**Repair Cost:** n/a

**Pages:** 1

Manufacturer: ZALL JIHLAVAN airplanes, s. r. o., Znojemská 64, 58601 Jihlava, Czech Republic  
Web: [www.skyleader.aero](http://www.skyleader.aero); E-mail: [support@skyleader.aero](mailto:support@skyleader.aero)